

## Schedule and Documentation

James Mills



## **Project Direction**

## Preliminary Stages of Project

- Assemble Project Management team
- Fast Track Effort
  - Set up flexible system to quickly and accurately manage change and set up controls
  - Assemble experienced team
- Work Breakdown Structure
- Organization Structure
- Establish WBS Level 2 Management (and if possible Level 3 and if lucky to Level 4)
- Establish straightforward lines of communication to BNL Senior Management

## Weekly/bi-weekly meetings

- Project Management status meeting with senior BNL management and project/technical advisory committee
- sPHENIX Project Management meeting
- Subsystem technical and status meetings
- Engineering team status meeting
- Science status and coordination meeting
- Engineering/Technical coordination meeting




## **Project Documentation**

- ✓ Work Breakdown Structure
- ✓ PM Organization Structure
- ✓ High Level Top's Down Schedule (Anticipated CD Authorization)
- ✓ Preliminary Bottom's-Up Schedule
- ✓ Recommendation Tracking System (Comment Resolution Book)
- ✓ Preliminary Basis of Estimate Document
- ✓ Preliminary WBS Dictionary
- ✓ Draft NEPA Evaluation Document (Met with ESH and Draft by 12/31/15)
- ✓ PCDR
- ✓ Preliminary Contingency and Risk Analysis Document
- ✓ Integration (Detector Envelope) Drawing
- ✓ Preliminary Q/A and Project Configuration Management and Controls
- ✓ Preliminary Hazard Analysis Report (started)



## **Project Management Documentation**


#### Work Breakdown Structure






## **Project Management Documentation**

#### **Project Organization Structure**





### High Level Top's-Down Milestones



•Operating Funds are used for conceptual design between CD-0 and CD-1. Operating funds may also be used prior to CD-4 for R&D, NEPA, D&D, ES&H, transition, startup, and training costs. Non-federal funds from other sources that are considered capital funds and are included in the "Total line item cost" as OPC.


Good Practice—For the first year that TEC is requested, ensure that OPC is also requested for that year. The OPC will allow
the project to continue in a long CR until TEC is available and new starts are allowed.

•MIE funds are more flexible than Line Items. Moving OPC to TEC or vice versa is much easier than for Line-Item reprogramming since MIE funds are "batched."

•New Start is defined as the first use/appropriation of any TEC funds (including TEC PED) for both line items and MIEs project.



Preliminary Project Schedule – Detailed Bottom's-Up Schedule




- MS Project 2010 Schedule
- 1600+ Lines
- Predecessors/Successors
- Critical Path/Milestones
- Subsystem files merged into Master File

ID	WBS	Name	Duration	Start	Finish	С
112	1.09.04.07.05	Install Tracker	5 days	1/27/21	2/2/21	
113	1.09.04.07.06	Align/survey Tracker to magnet centerline	3 days	2/3/21	2/5/21	
114	1.09.04.07.07	Install Tracker cables and services	15 days	2/8/21	3/1/21	
115	1.09.04.07.08	ORR	5 days	2/23/21	3/1/21	
116	1.09.04.07.09	Complete Tracker Installation	0 days	3/1/21	3/1/21	
120	1.09.04.07.10	Complete Detector Construction	0 days	3/4/21	3/4/21	
121	1.09.04.07.11	Commission Tracker	40 days	3/5/21	4/29/21	
122	1.09.04.07.12	Complete Commissioning	0 days	4/29/21	4/29/21	

- M&S is considered Fixed Cost and is accrued at the start of a task.
- Labor is based on an hourly rate and is prorated across the task duration.



### Preliminary Schedule – Critical Path\*




#### **Schedule Float**

Cradle Baseplate – 190d Production Outer Hcal - 11d Production Inner Hcal – 56d Production EMCal – 153d

#### Tracker Production -->

Tracker Installation -->


Subsystem Commissioning



<sup>\*</sup> Critical Path shown has redundant, parallel - equal duration tasks removed for clarity.




Preliminary Schedule – Secondary Critical Path



Outer HCal Production -->


Detector Construction (All Subsystems) -->


Subsystem Commissioning






## Preliminary Schedule – Labor Breakdown (HCal Example)









sPHENIX Fixed Cost By Subsys(NO Tracker)



## **Project Documentation**

## Recommendation Tracking System (Comment Resolution Book)

#### sPHENIX Recommendations Tracking System

Click on column header to sort. Click on recommendation id to edit.

m Fisc	.03	vel	Status	wbs	WBS name	Review	Recomm endation	Originator	Assign ed on	Responsible	Resolution Comment	Resolved on	A ck via
1 201:	5 Inter	ernal (	Closed	1.2	Magnet	Magnet Review	Continue with plan for the 100A test (or as high current as possible with the same instrumentation) at a site suitable for 1000A or full field test with a strong recommendation to perform full field test prior to DOE review	P. Pile, Chair	2014-12- 16	K. Yip	Sphenix has developed a plan for performing Low Field/High Field testing in B9112. Presentation of this plan to lab senior management will be done by 4/30/2015		
2 2013	5 Inter	rnal	open	1.2	Magnet	Magnet Review	Conduct a study of requirements for a full field test; simple return yoke design, power supply and quench protection.	P. Pile, Chair	2014-12- 16	K. Yip	Design of a yoke return for a full field test was performed. Detail design to follow.	2015-04- 07	
<u>3</u> 2013	5 Inter	rnal	open	1.2	Magnet	Magnet Review	Perform a full field test, if possible, in bldg. 912 before the magnet is moved to 1008. 2	P. Pile, Chair	2014-12- 16	K. Yip	Yes, this is being addressed (see No. 1 above).	2015-04- 07	
4 201:	5 Inter	ernal (	Closed	1.2	Magnet	Magnet Review	Resolution of management team issues for installation and testing of the magnet in 1008 will require C-AD management and ALD involvement as support for this effort will come at the expense of ongoing projects.  Recommendation: Work with the ALD and C-AD management to solve this problem ASAP.		2014-12- 16	E. O'Brien/J. Mills	Level 2 Manager for Manget has been assigned by CA.	2015-04- 07	
		$\dashv$					Installation and testing of the Magnet in the						$\vdash$



12

## **Project Documentation**

## Preliminary Basis of Estimate Document

<u></u>	sPHENIX Detector	Date of Est: 10/1/2015
PH ENIX	Relativistic Heavy Ion Collider	Prepared by: D. Phillips
<b>MLII</b> ₩ <b>FIIIV</b>	BASIS of ESTIMATE (BoE)	DocNo. (refer Rev. Log):
VBS number: 1.	2.3.3.1.3 WBS Title: Procure/Fabricate F	PS-Mag-QD DC Hook-up Parts
WBS Dictionary	Definition: Refer. WBS Dictionary	
Type (e	* * - Halk-of Edy.	
••	check all that apply):	
Work Con Existing P	nplete turchase Order	
Catalog Li	isting or Industrial Construction Database	
	ted Vendor Quotation based on Drawings/ Sketches/ Sp Estimate by Vendor/Fabricator based on Sketches, Dra	
x Engineerin	ng Estimate based on Similar Items or Procedures	wings, or other wither Correspondent
Engineerir		
	ng Estimate based on Analysis	
Expert Op	inion	
Expert Opi	inion uments (including but not limited to):	20 WOD + 50 WCB PS) v \$16/ft = \$48k
Expert Opi Supporting Docu 535mcm cable = Lugs = 10 locatio	inion iments (including but not limited to): 12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25° nos x 12 lugglocation x \$25(Mug = 83k	DR-WCB + 50' WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu 535mcm cable = Lugs = 10 locatio	inion  ments (including but not limited to):  12cables x (50' PS-WCB+50' WCB-Mag+50' Mag-DR+25' ons 12 lugs/location x \$25'lug = \$3k uss (WCB) Farts = \$3k	DR-WCB + 50' WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu 535mcm cable = Lugs = 10 locatio Water Cooled Bu Cable Tray Parts Miscellaneous Pa	inion iments (including but not limited to): 12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25° nos x 12 lugs/location x \$25/lug = \$3k uss (WCB) Parts = \$3k s = \$4k	DR-WCB + 50' WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu 535mcm cable = Lugs = 10 locatio Water Cooled Bu Cable Tray Parts	inion iments (including but not limited to): 12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25° nos x 12 lugs/location x \$25/lug = \$3k uss (WCB) Parts = \$3k s = \$4k	DR-WCB + 50' WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu 535mcm cable = Lugs = 10 locatio Water Cooled Bu Cable Tray Parts Miscellaneous Pa	inion iments (including but not limited to): 12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25° nos x 12 lugs/location x \$25/lug = \$3k uss (WCB) Parts = \$3k s = \$4k	DR-WCB + 50° WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu S35mcm cable = Lugs = 10 locatio Water Cooled Bt Cable Tray Part Miscellaneous Pa Total = \$60k	inion  ments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  sr \$4k  arts = \$2k	DR-WCB + 50° WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu S35mcm cable = Lugs = 10 locatio Water Cooled Bt Cable Tray Part Miscellaneous Pa Total = \$60k	inion iments (including but not limited to): 12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25° nos x 12 lugs/location x \$25/lug = \$3k uss (WCB) Parts = \$3k s = \$4k	DR-WCB + 50° WCB-PS) x \$16/ft = \$48k
Expert Opi Supporting Docu 535mcm cable = Lugs = 10 locatio Water Cooled Br Cable Tray Part Miscellaneous Pa Total = \$60k	inion  ments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  sr \$4k  arts = \$2k	e Power Supply in 1008B to the Magne
Expert Opi Supporting Docu S3Smem cable = 1 Lugs = 10 location Water Cooled Bu Cable Tray Part Miscellaneous Pa Total = \$60k	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25° nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  arts = \$2k  Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the	e Power Supply in 1008B to the Magne
Expert Opi Supporting Docu \$35mc cable = Lugs = 10 locatio Water Cooled Br Cable Tray Fundaments Miscellaneous Pa Total = \$60k This estimat in 1008-IR, is	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  arts = \$2k   Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which ma  Used in Developing Estimate:	e Power Supply in 1008B to the Magne y be located in 1008B or 1008-IR).
Expert Opi Supporting Docu SUSmen cable = Lugs = 10 locatio Water Cooled Br Cable Tray Furth Wiscellaneous Pr Total = \$60k  This estimat in 1008-IR, :  Reusing Reusing	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugslocation x 525/lug = 53k  us (WCB) Parts = 53k  = 54k  Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which materials in the Dump Resistor (which materials in Developing Estimate:  existing PHENIX Magnet Water Cooled Buss (two paints)	e Power Supply in 1008B to the Magne y be located in 1008B or 1008-IR).
Expert Opi Supporting Docu \$35smc cable = 2 Lugs = 10 locatio Water Cooled Bt Cable Tray Fart Miscellaneous Pa Total = \$60k  This estimat in 1008-IR, 3  **Ssumptions**  Reusing modifica	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  arts = \$2k   Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which ma  Used in Developing Estimate:	e Power Supply in 1008B to the Magne y be located in 1008B or 1008-IR).
Expert Opi Supporting Docu \$35smc cable = 2 Lugs = 10 locatio Water Cooled Bt Cable Tray Furth Miscellaneous Pa Total = \$60k  This estimat in 1008-IR, 3  **Ssumptions**  Reusing modifica	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  = \$4k  arts = \$2k   Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which materials in Developing Estimate:  existing PHENIX Magnet Water Cooled Buss (two paintons) as the connection between 1008B and 1008-IR.	e Power Supply in 1008B to the Magne y be located in 1008B or 1008-IR).
Expert Opi Supporting Docu \$35smc cable = 2 Lugs = 10 locatio Water Cooled Bt Cable Tray Furth Miscellaneous Pa Total = \$60k  This estimat in 1008-IR, 3  **Ssumptions**  Reusing modifica	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  = \$4k  arts = \$2k   Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which materials in Developing Estimate:  existing PHENIX Magnet Water Cooled Buss (two paintons) as the connection between 1008B and 1008-IR.	e Power Supply in 1008B to the Magney y be located in 1008B or 1008-IR).
Expert Opi Supporting Docu \$35smc cable = 2 Lugs = 10 locatio Water Cooled Bt Cable Tray Furth Miscellaneous Pa Total = \$60k  This estimat in 1008-IR, 3  **Ssumptions**  Reusing modifica	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  = \$4k  arts = \$2k   Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which materials in Developing Estimate:  existing PHENIX Magnet Water Cooled Buss (two paintons) as the connection between 1008B and 1008-IR.	e Power Supply in 1008B to the Magney y be located in 1008B or 1008-IR).
Expert Opi Supporting Docu \$35smc cable = 2 Lugs = 10 locatio Water Cooled Bt Cable Tray Furth Miscellaneous Pa Total = \$60k  This estimat in 1008-IR, 3  **Ssumptions**  Reusing modifica	inion  iments (including but not limited to):  12cables x (50° PS-WCB + 50° WCB-Mag + 50° Mag-DR + 25°  nos x 12 lugs/location x \$25/lug = \$3k  us (WCB) Parts = \$3k  = \$4k  arts = \$2k   Base Estimate (explanation of the Work)  te is for materials for hook-up of the DC power from the including the hook-up to the Dump Resistor (which materials in Developing Estimate:  existing PHENIX Magnet Water Cooled Buss (two paintons) as the connection between 1008B and 1008-IR.	e Power Supply in 1008B to the Magney y be located in 1008B or 1008-IR).

	Material [\$]	Designer [d]	Engineer [d]	Tech [d]	Physicist [d]	Studen [d]
Subsystem:	60,000	x	x	X	×	x
S. Contingency Rules Ap  M4  Engineering Estimate based or Contingency Rules Ap  L4  Engineering Estimate based or Contingency Rules Ap  L4  Engineering Estimate based or Contingency Rules Ap  Engineering Estimate based or Engineering Esti	on Similar Item  pplied  on Similar Item  Is that may affer  inpleted by Sub- pact Assessmen	s ct scope, effe system Man: and t Matrix and	iger ) Risk Classifi	cation Ma		ketches,
<ul> <li>Potential problem:</li> <li>Mitigation:</li> </ul>					ion Matrix)	
<ul> <li>Technical/Scope Risk – (</li> <li>Potential problem:</li> <li>Mitigation:</li> </ul>						
	see Impact Ass	essment Mat	rix and Risk (	Classificat	ion Matrix)	

Page 1 Page 2



## **Project Documentation**

Preliminary Basis of Estimate Document

Rev. 1 Rev. 2 Rev. 3 Rev. 4 Rev. 5	Chan Dat
Rev. 1 Rev. 2 Rev. 3 Rev. 4	
Rev. 3 Rev. 4	
Rev. 4	
Rev. 5	

1. Project Title:		2.	3	3: PERSON RESPONSIBLE
		DATE	E:	
SPHENIX		02/1	17 N	1. Anerella
		/201	15	
4. WBS ELEMENT CODE			5. WE	BS ELEMENT TITLE
1.02.04.01 Magnet Mechanical Coil/Core Modific	CATIO	NS	Insta	LLATION/TESTING
·				
5. Index Line Number:	7. Ri	EVISIO	ON	8: REV. DATE
	Num	IBER A	AND	
1-1-1-1		JTHORIZATION:		N:
9. Approved Changes				-

#### 9. ELEMENT TASK DESCRIPTION

#### COST CONTENT:

THE COSTS ASSOCIATED WITH THIS ITEM ARE FOR BOTH LABOR AND MATERIALS. THE LABOR IS THE EFFORT BY ENGINEERS, TECHNICIANS AND OTHER PERSONNEL ASSOCIATED WITH THE PREPARATION OF THE MAGNET AND VALVE BOX FOR SHIPMENT FROM BUILDING 912 TO THE EXPERIMENTAL HALL, AND INSTALLATION, REASSEMBLY AND ALIGNMENT OF THE MAGNET AS DESCRIBED IN THE INFRASTRUCTURE DESIGN WBS DICTIONARY ENTRY. MATERIAL COSTS ARE FOR CONSUMABLES USED IN THE INSTALLATION AND ALIGNMENT OF THE MAGNET. ALL LABOR AND MATERIAL ESTIMATES FOR THIS ARE BASED ON ENGINEERING ESTIMATES.

#### TECHNICAL SCOPE:

THIS ITEM INCLUDES ALL TASKS REQUIRED FOR DISASSEMBLY OF THE VALVE BOX FROM THE MAGNET, PREPARATION OF THE MAGNET AND VALVE BOX FOR SHIPMENT FROM BUILDING 912 TO THE EXPERIMENTAL HALL, AND INSTALLATION, REASSEMBLY AND ALIGNMENT OF THE MAGNET AS DESCRIBED IN THE INFRASTRUCTURE DESIGN WBS DICTIONARY ENTRY.

MECHANICAL SUPPORT STRUCTURES (THOSE STRUCTURAL COMPONENTS OF THE SPHENIX DETECTOR WHICH INTEGRATE AND STRUCTURALLY SUPPORT THE DETECTOR SUBSYSTEM THAT COMPRISE THE MAGNET SUPPORT MOUNTING AND ASSOCIATED ALIGNMENT FEATURES).

#### WORK STATEMENT:

THE EFFORTS REQUIRED TO COMPLETE THIS WBS ITEM ARE DESCRIBED FOR THE VARIOUS SUBTASKS AS FOLLOWS:

MAGNET SYSTEM INSTALLATION AND ALIGNMENT - THIS TASK ENCOMPASSES DISASSEMBLY OF THE VALVE BOX FROM THE MAGNET IN BUILDING 912, PREPARATION OF MAGNET AND VALVE BOX FOR TRANSPORT TO THE EXPERIMENTAL HALL, REASSEMBLY OF THE VALVE BOX TO THE MAGNET IN THE EXPERIMENTAL HALL, IN SITU ADJUSTMENTS AND INSPECTIONS OF THE MAGNET AND ALIGNMENT OF THE MAGNET TO THE CALORIMETER.

DELIVERABLE: MAGNET INSTALLED AND ALIGNED TO CALORIMETER, READY TO BE POWERED AFTER UPPER CALORIMETER INSTALLATION.



# Project Documentation Preliminary WBS Dictionary

WBS Dictionary to Level 4


WBS 1.02.04.01 Dictionary



## **Project Documentation**


 PCDR/Science Report – Defines Science Requirements, and how they relate and help define Technical Requirements (Indico Site)





- Integration Envelope Drawing/Document
  - Define (early in project) detector subsystem envelopes and stay clear zones.
  - Establish reasonable buffer between components (owned by project management).
  - Establish interconnect regions for attachments and supports.

Rich Ruggiero to discuss in Breakout Presentation





## **Project Documentation**

## Preliminary Contingency and Risk Analysis Document

Irina Sourikova to discuss in Breakout Presentation

## Preliminary Q/A and Project Configuration Management Plan

Jack Eng to discuss in Breakout Presentation

#### Preliminary Hazard Analysis Report

Paul Giannotti to discuss in Breakout Presentation


- Risk Top-Down (Project Level and Subsystem Manager Level)
- Contingency
  - Top-Down-Global (for this review)
  - Bottoms-up Task Based Contingency Evaluation
    - ATLAS/DUNE Labor/Materials Contingency
    - BNL SBMS Technical/Cost/Schedule Contingency
- · Bring Quality Concepts into project
  - · Link BNL Quality Office Requirements to project
  - Link Standards Based Management System Requirements to Project
- Bring Configuration Management into project
  - Document Control
  - · Change Control
  - Lines of Approval
  - Define Interface and Approval requirements to other participating departments and institutions.
- Follow CA-D 2011 Safety Assessment Document (SAD)
- BNL ESH Requirements
- Safety Committees
  - Radiation Safety Committee
  - Experimental Safety Review Committee
  - Accelerator Systems Safety Review Committee
  - ALARA Committee



## **Back Up Slides**



## **Condensed Summary Tasks and Milestones**





## Condensed Summary Tasks and Milestones

ID (	9	Task Name	Duration	Start	Finish	2014	2015	2016	2017	2018	2019	2020 202	1
26		Install Pedistal Base and Upper Cradle	26 days	5/20/2019	6/25/2019						26 days 6/25/	19	
27		Awaiting First Sector Outer Hcal	160 days	6/25/2019	2/18/2020						160 da	ays 2/18/20	
28		Install Lower Half of Hcal	70 days	2/18/2020	5/26/2020							70 days 5/26/20	
29		Coil ready for delivery to Assembly Hall	0 days	7/15/2019	7/15/2019						<b>→</b> 7/15	/19	
30		Install Coil	13 days	5/27/2020	6/12/2020							13 days <b>m</b> 6/12/20	
31		Install Upper Half of Outer Hcal	30 days	6/12/2020	7/27/2020							30 days 7/27/20	
32		Reinstall Coil Valve Box in Assembly Hall	20 days	7/21/2020	8/17/2020							20 days 8/17/20	
33		Install Pole Tips and Complete Carriage	8 days	8/18/2020	8/27/2020							8 days <b>I</b> 8/27/20	
34		Assemble, Prealign, and Install Inner Hcal	87 days	6/17/2020	10/20/2020							87 days	20
35		Install EMCal	44 days	10/19/2020	12/22/2020							44 days	22/20
36		Awaiting Tracker	12 days	12/22/2020	1/11/2021							12 days [ 1/1	
37		Install Tracker	37 days	1/11/2021	3/4/2021							37 day	s 3/4/21
38		Complete Construction	0 days	3/4/2021	3/4/2021							<b>\$</b>	:/4/21
39		Perform Commissioning	40 days	3/5/2021	4/29/2021							40 d	lays 4/29/2
40		Ready for Beam	0 days	4/29/2021	4/29/2021								4/29/



